Daily Report

Project:Durham Meadows Pipeline InstallationDate:August 5, 2022

Location: Coginchaug Regional High School, Pickett Lane, Durham

Day of Week: Friday

Project #: AECOM: 60614871 **Report No:** 483

Contractor: Ludlow Construction

Weather Conditions

Conditions: Daylight hours: Partly cloudy. Wind variable 0-10 mph.

ubcontractors Workfor57

Temperature (°F): High 93°F Low 77°F

Cont	ract	ors	& Sı
Trade	#	Х	hrs
USACE			
Field Engineer	1	Х	8
Flow Tech	0	Χ	8
Matt Chlor	0	Χ	8
A&J Construction	0	Χ	8
Grela Well Drilling	0	Χ	8
Fazzino Plumbing	0	Χ	8
United Concrete	0	Χ	8
Knapp Engineering	0	Х	8
Apuzzo Electric	0	Х	8
Alarm Systems, Inc.	0	Х	8
A&R Electrical	0	Х	8

Trade	#	Χ	hrs
Ludlow Construction			
Superintendent	0	Χ	8
Safety Officer	1	Χ	8
Foreman	1	Χ	8
Dump truck Operator	1	Χ	8
Excavator Operator	1	Χ	8
Skid Steer/Bucket Loader	1	Χ	8
Laborers	3	Χ	8
Note that some persons operate			
Multiple pieces equipment.			
Sub-contractor	0	Χ	8
Municipal Police Detail	0	Χ	8
State Police Detail	0	Χ	8

Equipment in Use			
Type	#	х	hrs
Concrete/Asphalt Road Saw	0	Х	8
Dump truck	2	Х	8
Front-end Loader – Large	1	Х	8
Excavator - Small	1	Х	8
Excavator - Rubber Wheeled	1	Х	8
Skid Steer / Bucket Loader	1	Х	8
Rolling Compactor	0	х	8
Plate Compactor	0	Х	8
Jumping Jack Compactor	1	Х	8
Street Sweeper (Broce Broom)	1	Х	8
Material Hopper	0	Х	8
Cutoff saw	1	Х	8
Light Tower	0	х	8

Page:

1 of 9

Visitors:

High School Maintenance Supervisor.

Pipe Connections, Installations, and Other Work

Ludlow completing tie-in from new service line to high school/education offices. Cutting and capping old water well connection.

<u>Daily Activities – Miscellaneous Activities, Durham</u>

0730: Ludlow crew initiating excavation at existing water supply connection to high school building.

0830: Existing water supply pipe (4" iron pipe) exposed. High School maintenance supervisor goes to valve vault in Pickett Lane to turn off supply to building.

0900: Ludlow cuts pipe on either side of existing elbow adjacent to building wall and removes pipe section. Ludlow caps outlet end of existing pipe.

0915: Ludlow begins excavating a trench from the existing inlet pipe to the capped outlet end of the new supply line, approx. 15 feet away to the west.

1025: New supply line end exposed. Ludlow begins adding pipe and fittings to connect the two pipe ends.

1105: Pipe connection completed. Ludlow finishes adjusting and tightening fittings, adds thrust blocks at bends in pipe.

Res. Representative:	A. Bogucki	Date: 8/5/22

Daily Report

Project: Durham Meadows Pipeline Installation Date: August 5, 2022 Day of Week: Friday Location: Coginchaug Regional High School, Pickett Lane, Durham **Report No:** 483 Project #: AECOM: 60614871 Page: 2 of 9 **Contractor: Ludlow Construction**

1140: Ludlow clears away tools and supplies for pipe connection, takes lunch break.

1210: Ludlow begins backfilling pipe trench.

1430: Backfilling complete. Ludlow prepares to leave site.

Res. Representative:
A. Bogucki
Date: 8/5/22

Daily Report

Project:Durham Meadows Pipeline InstallationDate:August 5, 2022

Location: Coginchaug Regional High School, Pickett Lane, Durham

Day of Week: Friday

Project #: AECOM: 60614871 **Report No:** 483

Page: 3 of 9

Contractor: Ludlow Construction




Photo 1: Ludlow laborer beginning excavation of supply line at school building wall. Electrical conduits visible adjacent to sidewalk. View to the east.

Res. Representative:	A. Bogucki	Date:	8/5/22

Daily Report

Project:Durham Meadows Pipeline InstallationDate:August 5, 2022

Location: Coginchaug Regional High School, Pickett Lane, Durham

Day of Week: Friday

Project #: AECOM: 60614871 **Report No:** 483

Contractor: Ludlow Construction 4 of 9



Photo 2: 4-inch existing supply pipe exposed. View to the north.

Res. Representative: A. Bogucki	Date:	8/5/22
---------------------------------	-------	--------

Daily Report

Project:Durham Meadows Pipeline InstallationDate:August 5, 2022

Location: Coginchaug Regional High School, Pickett Lane, Durham

Day of Week: Friday

 Project #:
 AECOM: 60614871
 Report No:
 483

 Page:
 5 of 9

Contractor: Ludlow Construction



Photo 3: Ludlow making second cut to remove section of existing supply pipe at school wall. View to the east.

Res. Representative:

A. Bogucki

Date: 8/5/22

Daily Report

Project: Durham Meadows Pipeline Installation Date: August 5, 2022

Location: Day of Week: Friday

Location: Coginchaug Regional High School, Pickett Lane, Durham

Project #: AECOM: 60614871 **Report No:** 483

Contractor: Ludlow Construction Page: 6 of 9



Photo 4: Capping completed at end of existing supply pipe adjacent to school. View to the northwest.

Res. Representative:	A. Bogucki	Date:	8/5/22

Daily Report

Project:Durham Meadows Pipeline InstallationDate:August 5, 2022

Location: Coginchaug Regional High School, Pickett Lane, Durham

Day of Week: Friday

Project #: AECOM: 60614871 **Report No:** 483

Contractor: Ludlow Construction Page: 7 of 9



Photo 5: Completed pipe connection to new supply line at school wall, with thrust blocks added. View to the east.

Res. Representative: A. Bogucki Date: 8/5/22

Daily Report

Project:Durham Meadows Pipeline InstallationDate:August 5, 2022

Location: Coginchaug Regional High School, Pickett Lane, Durham

Day of Week: Friday

Project #: AECOM: 60614871 **Report No:** 483

Contractor: Ludlow Construction Page: 8 of 9



Photo 6: Ludlow laborer placing marker tape over new supply line. View to the south.

Res. Representative:	A. Bogucki	Date: 8/5/22

Daily Report

Project:Durham Meadows Pipeline InstallationDate:August 5, 2022

Location: Coginchaug Regional High School, Pickett Lane, Durham

Day of Week: Friday

Project #: AECOM: 60614871 **Report No:** 483

Contractor: Ludlow Construction Page: 9 of 9




Photo 7: Ludlow placing backfill over pipe trench. View to the north.

Res. Representative: A. Bogucki Date: 8/5/22