Location:

### **Daily Report**

Project: August 8, 2022 **Durham Meadows Pipeline Installation** Date: Day of Week: Monday

**Report No:** 484 AECOM: 6061487

Project #: Page: 1 of 7

**Contractor: Ludlow Construction** 

Weather Conditions

Conditions: Daylight hours: Most Sunny. Wind variable 0-6 mph.

Coginchaug Regional High School, Pickett Lane, Durham

Temperature (°F): High 90°F Low 74°F

Conti	ract	ors	& Sı	ubcontractors Workfor57
Trade	#	х	hrs	Trade
USACE				Ludlow Construction
Field Engineer	1	Х	8	Superintendent
				Safety Officer
Flow Tech	0	Χ	8	Foreman
Matt Chlor	0	Χ	8	Dump truck Operator
A&J Construction	0	Χ	8	Excavator Operator
Grela Well Drilling	0	Χ	8	Skid Steer/Bucket Loa
Fazzino Plumbing	0	Χ	8	Laborers
United Concrete	0	Χ	8	Note that some persons operat
Knapp Engineering	0	Х	8	Multiple pieces equipment.
Apuzzo Electric	0	Х	8	
Alarm Systems, Inc.	0	Х	8	Sub-contractor
A&R Electrical	0	Х	8	Municipal Police Deta
				Chaha Dalias Dahail

Contractors Worklors			
Trade	#	Χ	hrs
Ludlow Construction			
Superintendent	0	Χ	8
Safety Officer	0	Χ	8
Foreman	1	Χ	8
Dump truck Operator	0	Χ	8
Excavator Operator	1	Χ	8
Skid Steer/Bucket Loader	0	Χ	8
Laborers	2	Χ	8
Note that some persons operate			
Multiple pieces equipment.			
Sub-contractor	3	Χ	8
Municipal Police Detail	0	Χ	8
State Police Detail	0	Χ	8

Equipment in	Use	
Туре	#	x hrs
Concrete/Asphalt Road Saw	0	x 8
Dump truck	2	x 8
Excavator – Large	1	x 8
Excavator - Mid-Size	0	x 8
Excavator - Rubber Wheeled	0	x 8
Skid Steer / Bucket Loader	0	x 8
Rolling Compactor	1	x 8
Plate Compactor	0	x 8
Jumping Jack Compactor	0	x 8
Street Sweeper (Broce Broom	n) 1	x 8
Material Hopper	0	x 8
Cutoff saw	1	x 8
Light Tower	0	x 8
	·	

Visitors:

None.

#### Daily Activities Ludlow Construction, Water Service Installation activities, Durham, CT.

0741: Ludlow Construction is releasing all the water from the blow-off valve on the west side of the Regional District Superintendent building parking lot. The blow-off valve is being removed by disassembling it. Ludlow Construction uses a pump to take out the water from the excavation.

0825: Ludlow Construction continues to connect the 2-inch pipe that was recently installed to the existing sprinkler system vault.

0858: Ludlow Construction continues to connect the 2-inch pipe that was recently installed to the existing sprinkler system vault.

0958: Ludlow Construction has finished connecting the new fire service to the existing sprinkler system vault.

1045: Ludlow Construction has begun to backfill the excavated area.

1107: Ludlow Construction finishes up backfilling of the excavated area.

Res. Representative:	A. Mora	Date: 8/8/22

## **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	August 8, 2022
Location:	Coginchaug Regional High School, Pickett Lane, Durham	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	484
Contractor:	Ludlow Construction	Page:	<b>2</b> of <b>7</b>

1148: Ludlow Construction compacts the backfilled area with a compactor.

1247: Ludlow Construction is placing loam and seed on top of the excavated area. Loam is being raked by Ludlow Constriction's personnel. Ludlow Construction places seeds on top of the topsoil.

Res. Representative:	A. Mora	Date: 8/8/22

### **Daily Report**

Project: Durham Meadows Pipeline Installation Date: August 8, 2022

Leasting: Coginghous Regional High School Rickett Long Durham

Day of Week: Monday

Location: Coginchaug Regional High School, Pickett Lane, Durham

 Project #:
 AECOM: 6061487
 Report No:
 484

 Page:
 3 of 7

**Contractor:** Ludlow Construction



Picture 1: Ludlow Construction is disassembling a temporary blow-off valve that is in an excavation trench west of the District 13 regional superintendent parking lot.

Res. Representative:	A. Mora	<b>Date:</b> 8/8/22

**Daily Report** 

Project:Durham Meadows Pipeline InstallationDate:August 8, 2022

Location: Coginchaug Regional High School, Pickett Lane, Durham

Day of Week: Monday

 Project #:
 AECOM: 6061487
 Report No:
 484

 Page:
 4 of 7

**Contractor:** Ludlow Construction



Picture 2: Ludlow Construction is tying in a newly installed pipe to the existing District 13 sprinkler system vault.

Res. Representative:	A. Mora	<b>Date:</b> 8/8/22

### **Daily Report**

August 8, 2022 **Project: Durham Meadows Pipeline Installation** Date:

Location: Coginchaug Regional High School, Pickett Lane, Durham


> **Report No:** 484

Day of Week:

Monday

AECOM: 6061487 Project #: Page: **5** of **7** 

**Contractor: Ludlow Construction** 



Picture 3: Ludlow Construction is in an excavation trench west of the District 13 regional superintendent parking lot and have completed the tying the new fire service supply pipe to the existing fire service system.

Res. Representative:	A. Mora	<b>Date:</b> 8/8/22

### **Daily Report**


Project:Durham Meadows Pipeline InstallationDate:August 8, 2022

Location: Coginchaug Regional High School, Pickett Lane, Durham

Day of Week: Monday

**Project #:** AECOM: 6061487 **Report No:** 484

Contractor: Ludlow Construction Page: 6 of 7



Picture 4: Ludlow Construction is backfilling the trench excavation near the District 13 sprinkler system vault with a combination of soil, gravel, and sand with an excavator.

Res. Representative:	A. Mora	<b>Date:</b> 8/8/22

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:August 8, 2022

Location: Coginchaug Regional High School, Pickett Lane, Durham

Day of Week: Monday

**Project #:** AECOM: 6061487 **Report No:** 484

Contractor: Ludlow Construction Page: 7 of 7



Picture 5: Ludlow Construction is at an excavation trench west of the District 13 regional superintendent parking lot and has fully backfilled the trench by topping it off with loam. Ludlow construction uses an excavator, and personnel to rake the topsoil.

Res. Representative:         A. Mora         Date:         8/8/22
-------------------------------------------------------------------