

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	August 17, 2022
Location:	S. Main Street and the Shared Access Driveway, Durham	Day of Week:	Wednesday
Project #:	AECOM: 6061487	Report No:	491
Contractor:	Ludlow Construction	Page:	1 of 7

Weather Conditions			
Conditions:	Daylight hours: Overcast. Wind variable 0-1 mph.		
Temperature (°F):	High 75°F	Low	61°F

Contractors & Subcontractors Workforce				Equipment in Use			
Trade	#	x	hrs	Trade	#	X	hrs
USACE				Ludlow Construction			
Field Engineer	1	x	8	Superintendent	0	X	8
				Safety Officer	1	X	8
United Concrete	0	X	8	Foreman	1	X	8
West State Mechanical	0	X	8	Dump truck Operator	1	X	8
Farrar Filter Co. Inc.	0	X	8	Excavator Operator	1	X	8
Grela Well Drilling	0	X	8	Skid Steer/Bucket Loader	1	X	8
Fazzino Plumbing	0	X	8	Laborers	2	X	8
United Concrete	0	X	8	Note that some persons operate			
Knapp Engineering	0	x	8	Multiple pieces equipment.			
Apuzzo Electric	0	x	8				
Alarm Systems, Inc.	0	x	8	Sub-contractor	0	X	8
A&R Electrical	0	x	8	Municipal Police Detail	0	X	8
				State Police Detail	0	X	8

Visitors: None.

Pipe Connections, Installations, and Other Work

Ludlow worked on landscaping activities at the Booster Station and the water tank work zone on the Shared Access Driveway in Middletown.

Daily Activities – Landscaping activities, Middletown

Ludlow worked on landscaping activities at the Booster Station and the water tank work zone on the Shared Access Driveway in Middletown.

0705: Two laborers from Ludlow have mobilized to the water tank work zone and the Shared Access Driveway in Middletown to cut grass.

0837: Ludlow continues to cut grass inside of the security gate surrounding the water tank located east of the Shared Access Driveway in Middletown.

Res. Representative:	J. Meunier	Date:	8/17/22
-----------------------------	------------	--------------	---------

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	August 17, 2022
Location:	S. Main Street and the Shared Access Driveway, Durham	Day of Week:	Wednesday
Project #:	AECOM: 6061487	Report No:	491
Contractor:	Ludlow Construction	Page:	2 of 7

1006: Ludlow continues to cut grass inside of the security gate surrounding the water tank located east of the Shared Access Driveway in Middletown and on the north and south sides of the Shared Access Driveway.

1151: Ludlow continues to cut grass inside of the security gate surrounding the water tank located east of the Shared Access Driveway in Middletown and on the north and south sides of the Shared Access Driveway.

1233: Ludlow continues to cut grass on the north and south sides of the Shared Access Driveway.

1335: Ludlow is finished cutting grass at the water tank work zone and the Shared Access Driveway and has mobilized to the Booster Station located on S. Main Street to cut grass

1439: Ludlow continues to cut grass at the Booster Station.

Res. Representative:	J. Meunier	Date:	8/17/22
-----------------------------	------------	--------------	---------

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	August 17, 2022
Location:	S. Main Street and the Shared Access Driveway, Durham	Day of Week:	Wednesday
Project #:	AECOM: 6061487	Report No:	491
Contractor:	Ludlow Construction	Page:	3 of 7



Picture 1: Ludlow cutting grass to the southeast of the water tank that is located east of the Shared Access Driveway in Middletown within the security fence that surrounds the water tank. View to the southwest.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	August 17, 2022
Location:	S. Main Street and the Shared Access Driveway, Durham	Day of Week:	Wednesday
Project #:	AECOM: 6061487	Report No:	491
Contractor:	Ludlow Construction	Page:	4 of 7



Picture 2: Ludlow cutting grass to the west of the water tank that is located east of the Shared Access Driveway in Middletown within the security fence that surrounds the water tank. View to the west.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	August 17, 2022
Location:	S. Main Street and the Shared Access Driveway, Durham	Day of Week:	Wednesday
Project #:	AECOM: 6061487	Report No:	491
Contractor:	Ludlow Construction	Page:	5 of 7



Picture 3: Ludlow cutting grass on the north side of the Shared Access Driveway in Middletown. View to the northwest.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	August 17, 2022
Location:	S. Main Street and the Shared Access Driveway, Durham	Day of Week:	Wednesday
Project #:	AECOM: 6061487	Report No:	491
Contractor:	Ludlow Construction	Page:	6 of 7



Picture 4: Ludlow cutting grass to the northeast of the Booster Station located on S. Main Street in Middletown. View to the southwest.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	August 17, 2022
Location:	S. Main Street and the Shared Access Driveway, Durham	Day of Week:	Wednesday
Project #:	AECOM: 6061487	Report No:	491
Contractor:	Ludlow Construction	Page:	7 of 7



Picture 5: Ludlow cutting grass to the northeast of the Booster Station located on S. Main Street in Middletown. View to the northeast.