#### **Daily Report**

Project: August 25, 2022 **Durham Meadows Pipeline Installation** Date: Day of Week: Thursday Location: Maple Avenue, Durham

AECOM: 6061487 **Report No:** 497

Project #: Page: 1 of 9

**Contractor: Ludlow Construction** 

Weather Conditions

Conditions: Daylight hours: Sunny. Wind variable 0-6 mph.

Temperature (°F): High 90°F Low 66°F

Conti	ract	ors	& Sı	ubcontractors Workforce
Trade	#	х	hrs	Trade
USACE				Ludlow Construction
Field Engineer	1	Х	8	Superintendent
				Safety Officer
United Concrete	0	Χ	8	Foreman
West State Mechanical	0	Χ	8	Dump truck Operator
Northeast Rigging	0	Χ	8	Excavator Operator
Grela Well Drilling	0	Χ	8	Skid Steer/Bucket Loa
Fazzino Plumbing	0	Χ	8	Laborers
United Concrete	0	Χ	8	Note that some persons operat
Knapp Engineering	0	Х	8	Multiple pieces equipment.
Apuzzo Electric	0	Х	8	
Alarm Systems, Inc.	0	Х	8	Sub-contractor
A&R Electrical	0	Х	8	Municipal Police Deta

contractors worklored			
Trade	#	Χ	hrs
Ludlow Construction			
Superintendent	0	Χ	8
Safety Officer	1	Χ	8
Foreman	1	Χ	8
Dump truck Operator	1	Χ	8
Excavator Operator	1	Χ	8
Skid Steer/Bucket Loader	1	Χ	8
Laborers	2	Χ	8
Note that some persons operate			
Multiple pieces equipment.			
Sub-contractor	0	Χ	8
Municipal Police Detail	0	Χ	8
State Police Detail	0	Χ	8

Equipment in Use			
Type	#	х	hrs
Concrete/Asphalt Road Saw	0	х	8
Dump truck	1	Х	8
Excavator – Large	1	Х	8
Excavator - Mid-Size	0	Х	8
Excavator - Rubber Wheeled	0	Х	8
Skid Steer / Bucket Loader	0	Х	8
Rolling Compactor	0	Х	8
Plate Compactor	1	Х	8
Jumping Jack Compactor	1	Х	8
Street Sweeper (Broce Broom)	0	Х	8
Material Hopper	0	Х	8
Cutoff saw	1	Х	8
Light Tower	0	Х	8

Visitors:

None.

#### Pipe Connections, Installations, and Other Work

Ludlow worked on paving activities on the driveway located on the 212R Maple Avenue, Durham, property.

#### Daily Activities - Paving, Durham

Ludlow worked on paving activities on the driveway located on the 212R Maple Avenue, Durham, property.

0706: Ludlow has mobilized to the 212R Maple Avenue property to resume paving activities.

0729: Ludlow is compacting the 1.25" processed gravel that they placed on the footprint of the driveway at the 212R Maple Avenue property over the past two days as they prepare to place asphalt today.

0732: Ludlow prepares to place tack coat on the cut edge of pavement on the west side of the driveway at the 212R Maple Avenue property.

0757: Ludlow begins to place first 2" lift of asphalt on the west side of the 212R Maple Avenue driveway.

Res. Representative:	J. Meunier	Date:	8/25/22

#### **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	August 25, 2022
Location:	Maple Avenue, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	497
Contractor:	Ludlow Construction	Page:	<b>2</b> of <b>9</b>
	- <del>-</del>		

0836: Ludlow continues to place first 2" lift of asphalt on the west side of the 212R Maple Avenue driveway.

0912: Ludlow continues to place first 2" lift of asphalt on the west side of the 212R Maple Avenue driveway. Temperature of the asphalt is 311°F.

0954: Ludlow has almost finished placing the first lift of asphalt on the footprint of the driveway at the 212R Maple Avenue property.

1209: Ludlow arrives with a load of asphalt for the second and final lift they will be placing on the footprint of the driveway located on the 212R Maple Avenue property.

1223: Ludlow begins to place the second lift of asphalt on the driveway of the 212R Maple Avenue property. Asphalt temperature is 309°F.

1258: Ludlow begins to place the second lift of asphalt on the driveway of the 212R Maple Avenue property.

1348: Ludlow has placed the second lift of asphalt on the majority of the driveway at the 212R Maple Avenue property. Ludlow is currently placing a second lift of asphalt where the driveway apron meets Maple Avenue.

1413: Ludlow brings additional asphalt to the 212R Maple Avenue property as they work to finish placing a second lift of asphalt on the driveway apron.

1428: Ludlow has finished placing asphalt on the footprint of the driveway at the 212R Maple Avenue property.

Res. Representative:	J. Meunier	Date:	8/25/22


### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:August 25, 2022

Location: Maple Avenue, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 497

Page: 3 of 9



Picture 1: Ludlow compacting 1.25" processed gravel on the driveway footprint of the 212R Maple Avenue, Durham, property. View to the northwest.

Res. Representative:	J. Meunier	Date:	8/25/22

#### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:August 25, 2022

Location: Maple Avenue, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 497

Page: 4 of 9



Picture 2: Ludlow applying tack coating to the cut edge of existing pavement on the west side of the driveway footprint of the 212R Maple Avenue property. View to the southwest.

Res. Representative:	J. Meunier	Date:	8/25/22

#### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:August 25, 2022

Location: Maple Avenue, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 497

Page: 5 of 9



Picture 3: Ludlow placing the first of two lifts of asphalt on the footprint of the 212R Maple Avenue property driveway. View to the north.

Res. Representative:	J. Meunier	Date:	8/25/22	

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:August 25, 2022

Location: Maple Avenue, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 497

Contractor: Ludlow Construction Page: 6 of 9



Picture 4: Ludlow placing the first of two lifts of asphalt on the footprint of the 212R Maple Avenue property driveway. View to the west.

Res. Representative:	J. Meunier	Date:	8/25/22

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:August 25, 2022

Location: Maple Avenue, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 497

Contractor: Ludlow Construction Page: 7 of 9



Picture 5: Ludlow placing the second of two lifts of asphalt on the footprint of the 212R Maple Avenue property driveway. View to the north.

Res. Representative:	J. Meunier	Date:	8/25/22

### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:August 25, 2022

Location: Maple Avenue, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 497

Page: 8 of 9



Picture 6: Ludlow placing the second of two lifts of asphalt on the footprint of the 212R Maple Avenue property driveway where it connects with Maple Avenue. View to the northeast.

Res. Representative:	J. Mei	unier	Date	:	8/25/22	

#### **Daily Report**

Project:Durham Meadows Pipeline InstallationDate:August 25, 2022

Location: Maple Avenue, Durham Day of Week: Thursday

**Project #:** AECOM: 6061487 **Report No:** 497

Page: 9 of 9
Contractor: Ludlow Construction



Picture 7: Ludlow using a rolling compactor on the second lift of asphalt they placed on the footprint of the driveway on the 212R Maple Avenue property. View to the northwest.

Res. Representative:	J. Meunier	Date:	8/25/22