#### **Daily Report**

Project:	Durh	am N	Mead	ow	s Pipeline Installation				Date: Septemb		
Location:	Picke	ett La	ane ar	nd I	Main Street, Durham				Day of Week:	Thurs	sday
Project #:	AFCO	)M: (	60614	187					Report No:		502
									Page:	<b>1</b> c	of <b>14</b>
Contractor:	Ludlo	ow C	onstr	uct	ion					-	
											1
					Weather 0	Condi	tion	S			
Conditions:		Da	ayligh	t ho	ours: Sunny. Wind variable (	)-9 m	nph.				
Temperature (°F):			gh		2°F Low 57°F		•				
			1	1	ontractors Workforce	-			Equipment in Use		
Trade		# >	x hrs	<u>.</u>	Trade	#	Х	hrs	· · ·		x hrs
USACE					Ludlow Construction				Concrete/Asphalt Road Saw	0	x 8
Field Engineer		1 >	x 8		Superintendent	0	Х	8	Dump truck	1	x 8
					Safety Officer	1	Х	8	Excavator – Large	1	x 8
United Concrete		0 >	x 8		Foreman	1	Х	8	Excavator - Mid-Size	0	x 8
West State Mechanic	al	0 >	x 8		Dump truck Operator	1	Х	8	Excavator - Rubber Wheeled	0	x 8
Northeast Rigging		0 >	x 8		Excavator Operator	1	Х	8	Skid Steer / Bucket Loader	0	x 8
Grela Well Drilling		0 >	X 8		Skid Steer/Bucket Loader	1	Х	8	Rolling Compactor	0	x 8
Fazzino Plumbing		0 >	X 8		Laborers	2	Х	8	Plate Compactor	1	x 8
United Concrete		0 >	x 8		Note that some persons operate				Jumping Jack Compactor	1	x 8
Knapp Engineering		0 >	x 8		Multiple pieces equipment.				Street Sweeper (Broce Broom)	0	x 8
Apuzzo Electric		0 >	x 8	1					Material Hopper		x 8
Alarm Systems, Inc.		0 >	x 8		Sub-contractor	0	Х	8	Cutoff saw		x 8
A&R Electrical		0 >	x 8	1	Municipal Police Detail	0	Х	8	Light Tower		x 8
				1	State Police Detail	0	Х	8			
					-						
Visitors: None.											

#### Pipe Connections, Installations, and Other Work

Ludlow completed the installation of a 1" water service line at Station 517+73 on Pickett Lane, Durham. Ludlow placed loam and grass seed along the driveways of several properties in Durham.

#### Daily Activities - Installation of water service lines, Durham

Ludlow completed the installation of a 1" water service line at Station 517+73 on Pickett Lane, Durham.

0714: Ludlow begins to excavate to the south of the curb stop located at Station 517+73.

0739: Ludlow continues to excavate to the south of the curb stop located at Station 517+73 and is preparing to install a meter pit south approximately 7' south of the curb stop.

0811: Ludlow is building a form to pour a concrete pad around the backflow preventer they will install later this morning to the south of the meter pit they are in the process of installing to the south of the curb stop at Station 517+73.

Res. Representative:J. MeunierDate:9/01/22	Res. Representative:	J. Meunier	Date:	9/01/22	
--	----------------------	------------	-------	---------	--

#### **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	September 1, 2022
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	502
Contractor:	Ludlow Construction	Page:	<b>2</b> of <b>14</b>

0831: Ludlow has installed a meter pit 7' south of the curb stop located at Station 517+73 and has run a section of 1" copper pipe between the meter pit and the curb stop.

0851: Ludlow is hand-excavating to locate the 1" HDPE water line that they will tie into with the 1" copper water service line they started installing at Station 517+73.

0911: Ludlow continues to hand-excavate to locate the 1" HDPE water line that they will tie into with the 1" copper water service line they started installing at Station 517+73.

0941: Ludlow continues to hand-excavate to locate the 1" HDPE water line.

0946: Ludlow has not been able to locate the 1" HDPE water line within the footprint of the trench they are excavating for the placement of the 1" copper water service line that will tie into the HDPE line. Ludlow has now begun to excavate at the curb stop located at Station ~517+80 to locate 1" HDPE water line.

1016: Ludlow succeeds in locating the 1" HDPE water line within the footprint of the trench they are excavating for the placement of the 1" copper water service line that will tie into the HDPE line. Ludlow has already placed approximately half of the 1" copper water service line and has begun to cover the copper pipe with sand and caution tape.

1026: Ludlow continues to place sand followed by caution tape over the 1" copper water service line that they have installed so far.

1101: Ludlow has just joined the existing 1" HDPE water line to the 1" copper water line they installed today using a brass coupling. Ludlow has just placed a bed of  $\frac{3}{4}$ " stone around the backflow preventer they installed to the south of the meter pit. Ludlow will later pour a concrete pad on top of the  $\frac{3}{4}$ " stone bed to create a pad for the backflow preventer.

1139: Ludlow is backfilling over the remainder of the trench they excavated for the installation of a 1" copper water service line after they tied into the existing HDPE line water line.

1201: Ludlow is using a jumping jack to compact the native fill that backfilled into the trench they excavated during the installation of a 1" copper water service line. Ludlow is also performing general housekeeping at the work zone.

1239: Ludlow continues to perform general housekeeping at the work zone located at Station 517+73.

1258: Ludlow is placing and grading loam over the areas that were disturbed during the installation of a 1" copper water service line, the meter pit, and the backflow preventer.

1324: Ludlow continues to grade and seed the loam they are placing at Station 517+73.

#### Daily Activities – Other, Durham

Ludlow placed loam and grass seed along the driveways of several properties in Durham.

1405: Ludlow has mobilized to the 208 Main Street residence to place loam and grass seed on both sides of the property's driveway.

 Res. Representative:
 J. Meunier
 Date:
 9/01/22

#### **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	September 1, 2022
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	502
Contractor:	Ludlow Construction	Page:	<b>3</b> of <b>14</b>

1430: Ludlow has mobilized to the 303/305R Main Street property to place loam and grass seed on both sides of the property's driveway.

1438: Ludlow is placing loam around the shared driveway apron for the 312 and 316 Main Street, Durham, properties. Ludlow has also placed loam and grass seed on the north side of the driveway apron for the 327 Main Street property.

 Res. Representative:
 J. Meunier
 Date:
 9/01/22

### **Daily Report**

	· · · · · · · · · · · · · · · · · · ·		
Project:	Durham Meadows Pipeline Installation	Date:	September 1, 2022
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	502
Contractor:	Ludlow Construction	Page:	<b>4</b> of <b>14</b>



Picture 1: Ludlow excavating at Station 517+73 for the installation of a 1" copper water service line. View to the southeast.

Res. Representative:	
----------------------	--

J. Meunier

Date:

### **Daily Report**

Droject:	Durkers Maadawa Disalina Installatian	Date:	Sontombor 1 2022
Project:	Durham Meadows Pipeline Installation	Date.	September 1, 2022
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	502
Contractor:	Ludlow Construction	Page:	5 of 14



Picture 2: Curb stop located at Station 517+73 that Ludlow daylighted. View to the northeast.

#### **Daily Report**

	<b>7</b>		
Project:	Durham Meadows Pipeline Installation	Date:	September 1, 2022
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	502
Contractor:	Ludlow Construction	Page:	6 of 14



Picture 3: Meter pit that Ludlow installed at Station 517+73, with a section of 1" copper water service line that was run between the curb stop and the meter pit. View to the southeast.

### **Daily Report**

	-	
Durham Meadows Pipeline Installation	Date:	September 1, 2022
Pickett Lane and Main Street, Durham	Day of Week:	Thursday
AECOM: 6061487	Report No:	502
Ludlow Construction	Page:	7 of 14
	Pickett Lane and Main Street, Durham AECOM: 6061487	Pickett Lane and Main Street, Durham AECOM: 6061487 Report No: Page:



Picture 4: Ludlow placing caution tape over sand they just placed over the 1" copper water service line they are installing at Station 517+73.

Res. Representative:	J. Meunier	Date:	9/01/22

### **Daily Report**


Project:	Durham Meadows Pipeline Installation	Date:	September 1, 2022
Troject.	Durnam meadows ripenne instanation		•
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	502
Contractor:	Ludlow Construction	Page:	<b>8</b> of <b>14</b>



Picture 5: Backflow preventer and meter pit that Ludlow installed at Station 517+73. View to the north.

#### **Daily Report**

	, i		
Project:	Durham Meadows Pipeline Installation	Date:	September 1, 2022
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	502
Contractor:	Ludlow Construction	Page:	9 of 14



Picture 6: Ludlow connecting the 1" copper water service line that they ran from Station 517+73 to the south and then to the east to the existing HDPE water line.

#### **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	September 1, 2022
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	502
Contractor:	Ludlow Construction	Page:	<b>10</b> of <b>14</b>



Picture 7: Ludlow compacting backfill on the north side of a concrete form they placed around the backflow preventer at Station 517+73. View to the east.

#### **Daily Report**

	, i i i i i i i i i i i i i i i i i i i		
Project:	Durham Meadows Pipeline Installation	Date:	September 1, 2022
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	502
Contractor:	Ludlow Construction	Page:	<b>11</b> of <b>14</b>



Picture 8: Ludlow using a rolling compactor on the native fill they backfilled over the 1" copper water service line they installed starting at the curb stop located at Station 517+73. View to the northeast.

#### **Daily Report**

Durham Meadows Pipeline Installation	Date:	September 1, 2022	
Pickett Lane and Main Street, Durham	Day of Week:	Thursday	
AECOM: 6061487	Report No:	502	
Ludlow Construction	Page:	<b>12</b> of <b>14</b>	
	Pickett Lane and Main Street, Durham AECOM: 6061487	Pickett Lane and Main Street, Durham AECOM: 6061487 Report No: Page:	



Picture 9: Ludlow grading loam and spreading grass seed on the areas that were disturbed when they installed a meter pit, backflow preventer, and copper water service line starting at the curb stop located at Station 517+73. View to the west.

Res. Representative:

#### **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	September 1, 2022
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	502
Contractor:	Ludlow Construction	Page:	<b>13</b> of <b>14</b>



Picture 10: Ludlow placing loam and grass seed on both sides of the paved portion of the driveway located at the 208 Main Street, Durham, property. View to the southeast.

#### **Daily Report**

Project:	Durham Meadows Pipeline Installation	Date:	September 1, 2022
Location:	Pickett Lane and Main Street, Durham	Day of Week:	Thursday
Project #:	AECOM: 6061487	Report No:	502
Contractor:	Ludlow Construction	Page:	<b>14</b> of <b>14</b>



Picture 11: Ludlow placing loam and grass seed on both sides of the paved portion of the driveway located at the 303/305R Main Street, Durham, property. View to the north.