QUALITY ASSURANCE REPORT (QAR)												REPORT NUMBER 750				Page 1 of 1		
DAILY LOG OF CONSTRUCTION											DATE 06 Jan 2021 - Wednesday							
PROJECT Durham Mea		aterline	Reme	dial Desiç	gn							WJ19C						
CONTRACTOR Ludlow Construction Co., Inc.												WEATHER Weather Caused No Delay Temperature Min 0 °F Max 0 °F No Precipitation No Wind						
PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS												EMPEF	RATURE			WIND		
STRUCTURAL EXCA- BORROW EXCA- VATION VATION 0 % 0 %					KMENT 0 %	CONCR		STR	RUCTURE	0 %	MINIMUM	0 °F	MAXIMUM 0 °	°F		0 M	1PH	
5 A							X						24 HOUR PRE		TION			
HAS ANYT LEAD TO A		IGHT	YES (Explain)				INCHES 0.00				DING		М					
NUMBER OF GOVERNMENT											RIVER STAGE							
SUPERVISORY	ERVISORY OFFICE		LAYO	UT	INSPECTION		TOTAL		LABOR		FEET			TIME	IME			
0		0		0		1		1		0			0.0				М	
NUMBER SUPERVISORY	SKILLED			MPLOYEES DRERS	S TOTAL		NUMI FROM		SHIFTS TO	Tee	T 1	TO] 2 [3 ROM		ТО		
	SNILLL													KUIVI		10		
0 ^#ta	- ab a list o	of the follo		0 a) Major ita		0	•	0700	1530			M ation of	M ontractor pers		M		М	
Attach a list of the following. (a) Major items of equipment either idle or working, and (b) Number and classification of contractor personnel onsite. NOTE: if the contractor's Quality Control Report (QCR) contains the information it need not be repeated.																		
QA NARRAT Miscellaneo		arks an	nd Visit	ors to Pr	roject:				 Ur	nresolv	ed Issue:	No	Shift: 1	1				
Kurt Mintel Discussion		Grega	rio - the	ere are no	current ic	cing issu	es on th	₁e tank a	access roa	d.								
John Jenki NO issues					uld be ons	ite next \	WED to	cold pa	itch any ho	les or o	dips where	e neede	ed.					
Contractor	not onsi	te toda	y - sche	eduled for	r next wee	∍k.												
		-	,		•													
QA REPRESENTA	TIVE'S SI	GNATU	RE		DA	ATE			RE/F	PROJEC	T ENGR'S	INITIAL	.S	D/	ATE			