| QUALITY ASSURANCE REPORT (QAR)<br>DAILY LOG OF CONSTRUCTION | REPORT NUMBER<br>752 | Page 1 of 0 |
|---|---|---|
| | DATE<br>08 Jan 2021 - Friday | |

| PROJECT<br>Durham Meadows Waterline Remedial Design | CONTRACT NUMBER<br>W912WJ19C0002 |
|---|---|
| CONTRACTOR<br>Ludlow Construction Co., Inc. | WEATHER<br>Weather Caused No Delay<br>Temperature Min 0 °F  Max 0 °F<br>No Precipitation  No Wind |

| PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS | | | | | TEMPERATURE | | WIND |
|---|---|---|---|---|---|---|---|
| STRUCTURAL EXCA-VATION | BORROW EXCA-VATION | EMBANKMENT | CONCRETE | STRUCTURE | MINIMUM | MAXIMUM | |
| 0 % | 0 % | 0 % | 0 % | 0 % | 0 °F | 0 °F | 0 MPH |

| HAS ANYTHING DEVELOPED ON THE WORK WHICH MIGHT LEAD TO A CHANGE ORDER OR FINDING FO FACT? | [X] NO | 24 HOUR PRECIPITATION | |
|---|---|---|---|
| | [ ] YES (Explain) | INCHES<br>0.00 | ENDING<br>M |

| NUMBER OF GOVERNMENT EMPLOYEES | | | | | | RIVER STAGE | |
|---|---|---|---|---|---|---|---|
| SUPERVISORY | OFFICE | LAYOUT | INSPECTION | TOTAL | LABOR | FEET | TIME |
| 0 | 0 | 0 | 1 | 1 | 0 | 0.0 | M |

| NUMBER OF CONTRACTOR'S EMPLOYEES | | | | NUMBER OF SHIFTS | | [ ] 1 | [X] 2 | [ ] 3 | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| SUPERVISORY | SKILLED | LABORERS | TOTAL | FROM | TO | FROM | TO | FROM | TO | | |
| 0 | 0 | 0 | 0 | 0700 | 1200  M | M | M | M | M | | |

Attach a list of the following. (a) Major items of equipment either idle or working, and (b) Number and classification of contractor personnel onsite.
NOTE: if the contractor's Quality Control Report (QCR) contains the information it need not be repeated.

## QA NARRATIVES

**Work Performed Today:**  Unresolved Issue: No   Shift: 1

Kurt Mintell
Ludlow onsite. Three workers total.
Shimmed the trench on Haddam Quarter Road with HMA.
Using excavator (wheeled) and ride on roller to compact.

Sent pictures to John Jenkins of the repair - No issues today

**Safety:**  Unresolved Issue: No   Shift: 1

Kurt Mintell
Safety:
Signs used in road while working (Haddam Quarter) - no traffic issues.
PPE used as required.

No Safety Issues noted

| QA REPRESENTATIVE'S SIGNATURE | DATE | RE/PROJECT ENGR'S INITIALS | DATE |
|---|---|---|---|
| | | | |