

QUALITY ASSURANCE REPORT (QAR) DAILY LOG OF CONSTRUCTION					REPORT NUMBER 853		Page 1 of 0		
					DATE 19 Apr 2021 - Monday				
PROJECT Durham Meadows Waterline Remedial Design					CONTRACT NUMBER W912WJ19C0002				
CONTRACTOR Ludlow Construction Co., Inc.					WEATHER Weather Caused No Delay Temperature Min 66 °F Max 53 °F No Precipitation No Wind				
PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS					TEMPERATURE		WIND		
STRUCTURAL EXCA- VATION	BORROW EXCA- VATION	EMBANKMENT	CONCRETE	STRUCTURE	MINIMUM	MAXIMUM			
0 %	0 %	0 %	0 %	0 %	66 °F	53 °F	0 MPH		
HAS ANYTHING DEVELOPED ON THE WORK WHICH MIGHT LEAD TO A CHANGE ORDER OR FINDING FO FACT?					24 HOUR PRECIPITATION				
					INCHES		ENDING		
					0.00		M		
NUMBER OF GOVERNMENT EMPLOYEES					RIVER STAGE				
SUPERVISORY	OFFICE	LAYOUT	INSPECTION	TOTAL	LABOR	FEET	TIME		
0	0	0	2	2	0	0.0	M		
NUMBER OF CONTRACTOR'S EMPLOYEES				NUMBER OF SHIFTS					
				<input type="checkbox"/> 1 <input checked="" type="checkbox"/> 2 <input type="checkbox"/> 3					
SUPERVISORY	SKILLED	LABORERS	TOTAL	FROM	TO	FROM	TO	FROM	TO
0	0	0	0	0700	1500 M	M	M	M	M
<p>Attach a list of the following. (a) Major items of equipment either idle or working, and (b) Number and classification of contractor personnel onsite. NOTE: if the contractor's Quality Control Report (QCR) contains the information it need not be repeated.</p>									
QA NARRATIVES									
Contractor/Subcontractor & Area of Responsibility for Work:					Unresolved Issue: No		Shift: 1		
Kurt Mintell Ludlow is onsite.									
Work Performed Today:					Unresolved Issue: No		Shift: 1		
Kurt Mintell Contractor is mobilizing equipment & Water main components to the tank site in preparation to install the water main connections to the Altitude Vault and water tank.									
Flush water main on 68 in preparation for chlorination.									
Safety:					Unresolved Issue: No		Shift: 1		
Kurt Mintell Safety Inspection:									
1. PPE good									
2. Traffic pattern/control - none needed today.									
3. Working in excavation - YES , trench box meets requirement.									
4. Muddy & trip hazards identified.									
4. Situational awareness while working around heavy equipment.									
QA REPRESENTATIVE'S SIGNATURE				DATE		RE/PROJECT ENGR'S INITIALS		DATE	