										_							
QUALITY ASSURANCE REPORT (QAR)										_	REPORT NUMBER 1023				Page 1 of 0		
DAILY LOG OF CONSTRUCTION									DATE	DATE 06 Oct 2021 - Wednesday							
PROJECT Durham Meadows Waterline Remedial Design											CONTRACT NUMBER W912WJ19C0002						
CONTRACTOR											WEATHER						
Ludlow Construction Co., Inc.											Weather Caused No Delay Temperature Min 54 °F Max 73 °F No Precipitation No Wind						
PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS											TEMPERATURE WIND						
STRUCTURAL EXCA- BORRON VATION					EMBANKMENT CC		CONCRETE		TRUCTURE		М	MAXIMUM					
0 %			0 %		0 %		0 %		0 %		54 °F	°F 73 °F		0 MPH			
HAS ANYTHING DEVELOPED ON THE WORK WHICH MIGHT										24 HOUR PRECIPITATION INCHES ENDING							
LEAD TO A CHANGE ORDER OR FINDING OF FACT										INCHES	INCHES 0.00				М		
N		NUMBI	NUMBER OF GOVERN		MENT EMPLOYEES						RIVER			TAGE			
SUPERVISORY	OFF	ICE	LAYO	UT	INSPECT	TON	TOTAL	LA	BOR	FEET				TIME			
0		0	1	0		0		0	(0.0			М		
NUMBE	R OF (CONTRACTO	R'S EM	IPLOYEES	3		NUMBE	R OF SHIF		1	X	2	\Box	3			
SUPERVISORY	SKII	LED	LABO	RERS	TOTAL		FROM	ТО	F	ROM	TO		FROM	M	ТО		
0		0		0		0			м		М	М		М	М		
		ist of the follo	wing (s		ems of equi		<u> </u>	orking and		and classifi			ersonr		101		
		the contractor									cation of	contractor pe	5130111	ici orisito.			
QA NARRA	TIVE	S															
Work Perfo	rmed	Today:							Unresol	ved Issue:	: No	Shift	:: 1				
Joseph Cı	urrier																
Ludlow cr																	
Working a	t the t	ank site inst	talling a	a block re	etaining w	all (versa	a lock CMI	J) along th	ie upper ac	cess road	-						
1 Pock of	ncoun	tered - NA															
2. Cut parking lot - NA 3. Remove bushes/trees - NA																	
4. Flagger	r being	g utilized - N	Α														
AR Electri	ic - No	ot onsite toda	ay.														
DN Tank -	- Not o	onsite today															
Fazzino P filter syste		ng - At 17 &	24 Ma	aiden Ln	and 325 N	/lain Stre	et. Two pl	umbers ar	e completir	ng the final	l water t	tie in and re	mova	al of old			
,		al - Not on s	site tod	lay.													
Safety:									: No	Shift	:: 1						
Joseph Cı	ns items:	:															
		- all persor				when en	tering the	site.									
		n/control - N cavation - y				retainin	n wall no t	trenchina	nday								
		vareness wh								ni excavato	or						
		techniques															
		ussion prior				nat worke	ers will wea	ar a mask	when enter	ring some	one's ho	ome					
		e trench - N				. 1. 1 1 14	l. l. !	Parlata									
		eing driven o / full cover v				enina wit	n tiasning	lights.									
		tection used				erations	- NO ledg	e removal	today.								
	0.		·	, ,	•		J		•								
REVIEW \																	
NO new s	arety	issues to rev	view to	day.													
QA REPRESENTA	ATIVE"	S SIGNATUR	E		D.A	ATE			RE/PROJĒ	CT ENGR'S	S INITIAL	S		DATE			
					1									1			