QUALITY ASSURANCE REPORT (QAR) DAILY LOG OF CONSTRUCTION PROJECT											REPORT NUMBER 568 DATE 08 Jul 2020 - Wednesday				Page 1 of 0		
											CONTRACT			ay			
Durham Mea	adow	s Waterlin	e Rem	edial Desiç	gn						W912WJ19C0002						
CONTRACTOR Ludlow Construction Co., Inc.											WEATHER Weather Caused No Delay Temperature Min 0 °F Max 0 °F No Precipitation No Wind						
	РО	RTION OF	SCHEE	DULED DAY	SUITABLE	FOR OP	ERATIONS	3			TE	MPEF	RATURE			WINI	ס
STRUCTURAL EX VATION	CA- 0 %	BORROW VATION	EXCA-		MENT 0 %	CONCRI	ETE 0 %	STRUC	CTURE	0 %	MINIMUM	0°F	MAXIMUM	0°F			0 MPH
	<u> </u>		0 //	<u>" </u>	0 70	<u> </u>		1		0 70			24 HOUR P		ITATION		J 1VII 11
HAS ANYTHING DEVELOPED ON THE WORK WHICH MIGHT LEAD TO A CHANGE ORDER OR FINDING FO FACT? VES. (Explain)										INCHES				ENDING			
LEAD TO A	A CHA	INGE ORD	ER UR	FINDING FO	FACT?		☐ \	YES (Exp	lain)				0.00				M
		NUM	IBER O	F GOVERNI	MENT EMP	LOYEES							RIVE	R STA	GE		
SUPERVISORY	OFF	ICE	LAY	OUT	INSPECT	ION	TOTAL		ABOR		FEET				TIME		
0			0	0		2		2		0			0.0				M
NUMBER	ROF	CONTRACT	TOR'S E	MPLOYEES	3		NUMBE	R OF SI	HIFTS	[1	Х	2		3		
SUPERVISORY	SKII	LED	LAB	ORERS	TOTAL		FROM	TC)	FR	ОМ	ТО		FROM	1	то	
0			0	0		0	0.	700	1530	м	М	1	М		М		M
											nd classificati	ion of	contractor p	ersonn	el onsite.		
QA NARRA			tor's Qu	ality Contro	Report (Q	CR) contai	ins the info	rmation i	need not b	oe repe	eated.						
Contractor/		_	r & Are	a of Resp	onsibility	for Worl	k:		Unr	esolve	ed Issue: No	0	Shif	t: 1			
Robert Ch Project inv		installing	water	main from	a new Mid	ddletown	Water Ta	nk into	Durham a	nd tyiı	ng into hom	nes &	businesse	es:			
Prime Con Subcontra Subcontra Subcontra Subcontra Work Perfor Robert Ch Billy's Cret 2 - State F Route 17: Installed - John's Cret 1 - Certifie Continued Pay Items: 1. Police - 2. Flagger 3. Illumina 4. Curb sto 5. Ledge F 6. 1" Curb 7. 1" Coop	ctor: ctor - cto	ACE Cons - John Tur NY-CON Veilleux (Today: b stops gger stall the 30 ate Police igns - yes val pe -	sulting rner Cc N - Rep Concre Concre	- SŠHO Ro onsulting - pairing of the te cutting -	ob Peddico Compactione traffic lo Saw cutti	ord & CC on testing pops ng	C Jerry B	randon			ed Issue: No		Shif				
		•	V cn 4-	7					Onr	CSUIVE	zu issue. Ni	U	SIIII	L. I			
Kurt Minte 31: 1'curb 34: 1" cop 61 Sawcut	stops per pi	installed pes = 113	at STA 3 LF	\ -173+19 &		OVER E	ST.QTY)										
54: Rock & Results of C	& bou	lder excav	/ation=	4.25 CY				s Takor	ı: Hon	esolve	ed Issue: N	0	Shif	†· 1			
Robert Ch John's cre	ristie w: Fo now 36" p	llow up in installed : ipe up the	spectic 2 - 20 f e emba	on of the st oot section nkments.	ream cros as of the 3	sing. The 6" pipe w	ey installe hich clear	d the se	cond sect oan of the	tion of	the 36" pip m so they c	e and	d welded th	hem to			
											ed on the gr o be clogge		and no				

Follow up inspection of Billy's crew installing curb stops on route 17 in Durham. They are being installed per the drawings. Follow up inspection of the saw cutting for the curb stops on route 17. **Verbal Instructions Given to Contractor:** Unresolved Issue: No Shift: 1 Robert Christie None to report. Miscellaneous Remarks and Visitors to Project: Unresolved Issue: No Shift: 1 Robert Christie Water encountered while excavating: Water was observed in the trench on Maiden lane for the hydrant assembly installation. PR Comments, encounters or issues: None to report. CT DOT onsite or communication: None to report. Miscellaneous Remarks and Visitors to Project: Unresolved Issue: No Shift: 1 Robert Christie Jerry - QC Rob P - SSHO John Pio - Superintendent Mike Pio - onsite **USACE - Kurt Mintell** AECOM - Joel and was onsite providing extra oversight of the contractor. Mike Cunningham JTC Consulting Miscellaneous Remarks and Visitors to Project: Unresolved Issue: No Shift: 2 Kurt Mintell Met with Heather at 36 Maiden Lane and Harry Feinberg (neighbor) along with Mike Cunningham. Heather claimed Ludlow had damaged her mailbox while installing hydrant - there is a dent. MC agreed to replace and loam and seed around the mailboxes. Also agreed to straighten out Harrys mailbox. No issue at this time Safety: Unresolved Issue: No Shift: 1 Robert Christie Noted portable hand wash station on back of tool truck, cleaning supplies nitrile gloves, face masks. Workers fill out daily forms indicating they are not demonstrating any symptoms of COVID 19 and turning into SSHO. Noted proper PPE while cutting Steel pipe with cut off saw. 2. Discussed situational awareness while working around heavy equipment, and while allowing residents to use the shared driveway while under construction 3. Situational awareness not to work in close proximity to each other (COVID PREVENTION) 4. Trench box being used for all excavations while working in trench. QA REPRESENTATIVE'S SIGNATURE DATE RE/PROJECT ENGR'S INITIALS DATE