QUALITY ASSURANCE REPORT (QAR)						REPORT NUMBER 580  DATE 20 Jul 2020 - Monday				Page 1 of 0						
DAILY LOG OF CONSTRUCTION																
PROJECT Durham Mea	adows Waterline	e Reme	dial Desig	ın						CONTRAC W912V						
CONTRACTOR				,						WEATHE	R					
Ludlow Constr	ruction Co., Inc.									Tempe	rature I	ed No Delay Min 0 °F Ma on No Wind				
	PORTION OF	SCHEDU	JLED DAY	SUITABLE	FOR OP	ERATION	S			Т	EMPE	RATURE			WIND	
STRUCTURAL EXIVATION	CA- BORROW VATION	EXCA-	EMBANK	MENT	CONCR	ETE	STR	UCTURE		МІМІМИМ		MAXIMUM				
VATION	0 %	0 %		0 %		0 %	%		0 %		0 °F		0 °F	T. T. O. I.	0	MPH
HAS ANYT	HING DEVELOPI	ED ON T	HE WORK	WHICH MI	GHT	X	NO			INCHES		24 HOUR P		ENDING		
LEAD TO A	A CHANGE ORDE	ER OR FI	NDING FO	FACT?			YES (E	Explain)		INCITES		0.00	ľ	LINDING		М
	NUM	BER OF	GOVERNI	MENT EMP	LOYEES								R STAG	 E		
SUPERVISORY	OFFICE	LAYO		INSPECT		TOTAL		LABOR		FEET				ГІМЕ		
1			0		1		2		0			0.0				М
NUMBER	R OF CONTRACT	OR'S EM	1PLOYEES	3		NUMB		SHIFTS		<u>.</u> 1	X	2	<u></u> 3	3		
SUPERVISORY	SKILLED	LABO	RERS	TOTAL		FROM		ТО	FR	OM	TO	_	FROM		TO	
0		0	0		0		0700	1530	м		М	М		М		М
	ach a list of the fol										ation of	contractor p	ersonne	el onsite.		
	TE: if the contract	tor's Qua	lity Control	Report (Q0	CR) conta	ins the info	ormatio	n it need not	be repe	eated.						
QA NARRAT	med Today:							Uni	esolv	ed Issue: I	Nο	Shif	t· 1			
Kurt Minte	•							Oili	CSOIV	ou 133uc. 1	10	Onn				
On 17:																
Install curb	stops to busin	esses at	t:													
1. Mobil G	•															
Tank Site:																
2 Workers	from DN tank b	ouilding	saw horse	es - fabric	ating for	ms										
Pickett Lar	ne:															
Continue in	nstalling 12" wa	iter mair	n at the st	ream cros	sing.											
QTYS:																
0031: 1" C 0034: 1" C	Vater Corporation  Vaturb Stop at Gra  Vater Pipe = 77  Varer State Road	appos M 7.5		1												
TORWARI	T OF 12 INCH <sup>-</sup> DS MAIDEN LA FORED STREA	NE.			2 TO 53	2+93. TIE	ED IN 1	12 INCH WA	ATER	MAIN ON	SIDE	OF STREA	AM GC	ING		
Verbal Instructions Given to Contractor:						Unr	esolve	ed Issue: I	No	Shif	t: 1					
Kurt Mintel	II Ensure no	addition	al tank de	eliveries go	to the I	Barones a	at 224	Talcott								
along with	nove the dirt pil an explanation	- CLOS	ED		e league	e field - id	lentifie	d by Karen	Keane	e as a Safe	ety iss	ue. Photos	sent to	o KKean	e	
	ous Remarks a			•		9 <b>6</b> :				ed Issue: I	No	Shif	t: 2			
Kurt Minte	ll Noted dam	aged cu	ro on Pic	kett under	guardra	ııı trom st	ream c	crossing - Kl	==P(	JYEN .						
	ous Remarks a	nd Visit	ors to Pr	oject:				Unr	esolve	ed Issue: I	No	Shif	t: 1			
Kurt Mintel	II OM onsite															
	ous Remarks a	nd Visit	ors to Pr	oject:				Unr	esolve	ed Issue: I	No	Shif	t: 1			
Kurt Mintel		- "-	_	•												
Left a pain	t mark for Arma on- the CBYD t														)	

OPEN

DOT Correspondence - NONE				
Safety:		Unresolved Issue: No	Shift: 1	
Kurt Mintell Email to SSHO (Rob P.) to ensure proper COVID town- cc ed Mike Pio on the email.	19 steps are being taken - espe	cially with the Tank Crew since th	ey are form	out of
All materials removed from the corner of Pickett a	and the little league fields (RESO	LVED)		
Noted Traffic Control:				
1. on 17 1 certified flagger & 1 CSP. 2. Pickett Lane - 1 Certified flagger by Maiden La	ne.			
PPE & Trench Box:				
trench boxes being used on 17 & the stream color.     PPE noted				
3. Hot temperature discussion - staying hydrated	reviewed.			
REPRESENTATIVE'S SIGNATURE	DATE	RE/PROJECT ENGR'S INITIALS		DATE