QUALITY ASSURANCE REPORT (QAR) DAILY LOG OF CONSTRUCTION	REPORT NUMBER 611	Page 1 of 1
	DATE 20 Aug 2020 - Thursday	

PROJECT Durham Meadows Waterline Remedial Design	CONTRACT NUMBER W912WJ19C0002
CONTRACTOR Ludlow Construction Co., Inc.	WEATHER Weather Caused No Delay Temperature Min 0 °F Max 0 °F No Precipitation No Wind

PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS					TEMPERATURE		WIND
STRUCTURAL EXCA-VATION	BORROW EXCA-VATION	EMBANKMENT	CONCRETE	STRUCTURE	MINIMUM	MAXIMUM	
0 %	0 %	0 %	0 %	0 %	0 °F	0 °F	0 MPH

HAS ANYTHING DEVELOPED ON THE WORK WHICH MIGHT LEAD TO A CHANGE ORDER OR FINDING FO FACT?	[X] NO [ ] YES (Explain)	24 HOUR PRECIPITATION	
		INCHES 0.00	ENDING M

NUMBER OF GOVERNMENT EMPLOYEES						RIVER STAGE	
SUPERVISORY	OFFICE	LAYOUT	INSPECTION	TOTAL	LABOR	FEET	TIME
0	0	0	1	1	0	0.0	M

NUMBER OF CONTRACTOR'S EMPLOYEES				NUMBER OF SHIFTS		[ ] 1 [X] 2 [ ] 3					
SUPERVISORY	SKILLED	LABORERS	TOTAL	FROM	TO	FROM	TO	FROM	TO		
0	0	0	0		M	M	M	M	M		M

Attach a list of the following. (a) Major items of equipment either idle or working, and (b) Number and classification of contractor personnel onsite.
NOTE: if the contractor's Quality Control Report (QCR) contains the information it need not be repeated.

QA NARRATIVES

Work Performed Today: Unresolved Issue: No   Shift: 1

Kurt Mintell
Curb Stop Crew:
0028: 1" Corporations = 2 (238 & 228 Main Street)
0031:
0034: 1" Copper Pipe = 101.2 LF
0040: Pierce under sidewalk= 8 LF
0054: Ledge Removal - 2.29 CY
0061: Sawcut State Road

Jon Pio Crew
ITEMS:
26: 4 HYDRANT ASSEMBLIES INSTALLED: STA 916+40.5, 913+40, 906+88, AND 900+07.5
62: 16 FEET OF TOWN SAW CUT

Work Performed Today: Unresolved Issue: No   Shift: 2

Paul Paris   The tie into the main in front of 13 Maple Ave is happening today. The curb stop from the main line is 16 feet and from the curb stop to the house is 30 feet. Ludlow is working on getting a plumber to tie this house into the town water.

QA REPRESENTATIVE'S SIGNATURE	DATE	RE/PROJECT ENGR'S INITIALS	DATE