QUALITY ASSURANCE REPORT (QAR) DAILY LOG OF CONSTRUCTION												REPORT NUMBER 644				Page 1 of 0		
												DATE 22 Sep 2020 - Tuesday						
PROJECT Durham Meadows Waterline Remedial Design												CONTRACT NUMBER W912WJ19C0002						
CONTRACTOR		WEATHER																
Ludlow Construction Co., Inc.												Weather Caused No Delay Temperature Min 36 °F Max 61 °F No Precipitation No Wind						
PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS												TEMPERATURE WIND						
STRUCTURAL EXCA-VATION O % SORROW EXCA-VATION O % O M O M O M				MENT 0 %	CONCR	ETE 0 '		UCTURE	0 %	MINIMUM	36 °F	MAXIMUM	61 °F		0 MPH			
0 79 0 70 1					<u> </u>	<u> </u>		NO NO					<u>1</u> 24 HOUR P		TATION	<u> </u>		
HAS ANYTI LEAD TO A		IGHT	X	YES (E	xplain)		INCHES		0.00	E	NDING		м					
	JENT EMP	EMPLOYEES					RIVER STAGE						┪					
SUPERVISORY	OFFICE	FFICE LAY			INSPECT	SPECTION			LABOR		FEET			TIN				
0		0		0		0		0		0			0.0				М	
	OF CONTR	ACTO							SHIFTS	Les	1	X	2	3		TO.	4	
SUPERVISORY	SKILLED			RERS	TOTAL		FROM		TO		ROM	ТО		FROM		ТО		
0		0	<u> </u>	0		0	<u> </u>			М		M	M		M		М	
	ich a list of the											ation of	contractor p	ersonne	el onsite.			
QA NARRAT Work Perfor		/ :							Ur	resolv	ed Issue:	No	Shif	t: 2				
Paul Paris													sed down				١	
weeks. Up	recting traffi at the tank	site t							nk.	•					to three		١	
Work Perfor	-	/ :							Ur	resolv	ed Issue:	No	Shif	t: 2				
114: 823 L 116:275.48 117: 275.4 119: 4.44 S	7 - permane F State Sav 3 SY STA11 8 SY STA 1 SY Liver Sla	vcut 8+80 18+2 lb	0-122+7 20 -122	!+75														
Miscellaneo	us Remark	d Visite	ors to Pro	oject:				Ur	resolv	ed Issue:	No	Shif	t: 2					
	th Steve Wi trench is se														d headin	g		
OA DEDDEGENES	TIVE 0 0 0 0 1 0 1 1	A 71 17	<u></u>		15.	TE			I DE /S	ים יבי	T ENODIC	INITIAL					_	
QA REPRESENTA	TIVE'S SIGN.	AIUF	Œ		I DA	ΛTE			RE/P	KOJEC	T ENGR'S	INITIAL	.5		DATE			