## David F. Cash

**File No.:** 199701040

City and State: North Attleboro, MA

**General Impacts:** 0.57 acre

**Functions and Values Lost:** (From EA/SOF)

Groundwater Discharge Floodflow Alteration Toxicant Retention Wildlife Habitat (Diversity/Abundance)

Year(s) Mitigation Constructed: October 1999

## **Size and Type of Mitigation as Proposed:**

0.43 acre creation1.58 acres preservation

## **Proposed Functions and Values of Mitigation:**

Floodflow Alteration Groundwater Nutrient Removal Sediment/Toxicant Retention Wildlife Habitat

## **Mitigation Special Condition(s):**


2a. Permittee shall implement the grading and planting plan set forth on the plan entitled "Proposed Wetland Replication Plan in North Attleborough, Massachusetts" dated "March 12, 1998" in 1 sheet. This work shall be completed no later than the substantial completion of the development work at the site.


#### Remarks:

None

#### **Directions:**

Take I-95 south to the exit for Route 1 in Attleboro. Go north. When the road forks and Route 1 bears right, follow Route 1 but the site is just after a small strip mall on the left. Park there or at the Domino's Pizza which is immediately adjacent to one of the creation sites.





#### MITIGATION SITE FIELD DATA FORM

Site Name: David Cash File No.: 199701040

City/Town: North Attleboro State: MA Waterbody:

Monitor(s): McKee, Wright Date: 6-20-02

Was site constructed? yes

Is site wetland?

**Size of proposed wetland:** 0.43 acre

**Actual size of wetland:** app. 0.43 acre

**Landscape position:** 2 depressions surrounded

by steep to moderate inclines

Lat/Long Points: Site A N41.96885

W071.33749

Site C N41.96867 W071.33690

**Saved GPS Waypoint name:** DCASH (site C)

CASHA (Site A)

**GPS Tracking Log Name: TBD** 

**Perimeter:** TBD

**Surrounding land use:** 

Residential, industrial park

Is wetland function compromised by surrounding land use?

Both sites may experience runoff from lawns or parking lots and are easily accessible by people,

which may impact wildlife.

**Plant Health:** 

Good

**Invasive Species:** 

Site A: none

Site C: Lythrum salicaria (trace)

Wildlife Use:

Site A: bullfrog, green frog, Site C: bullfrog, green frog, red-winged blackbird, report of

snapping turtle

**Plants:** 

Site A:

Acer rubrum Alisma triviale

Bidens sp. Carex lurida Carex sp.

Carex sp. (ovales) Eleocharis sp. Galium sp.

Impatiens capensis Juncus effusus Lemna sp.

Lythrum salicaria Phalaris arundinacea

Poaceae spp.

Polygonum arifolium

Salix sp. Salix discolor Sambucus canadensis

Typha latifolia

Site C:

Acer rubrum

Alisma sp.

Betula populifolia

Bidens sp.

Carex sp. (ovales)

Carex lurida

Impatiens capensis

*Iris* sp.

Juncus effusus

Lemna sp.

Lythrum salicaria Poaceae sp. Rubus sp. Sambucus canadensis Typha latifolia Ulmus americana Vitis sp.

#### **Soils Data:**

Site A

DEPTH	HORIZON	MATRIX	REDOX	COMMENTS
0 - 1"	A	5Y 2.5/2	none	loamy medium sand
1+	В	10YR 3/2	2.5YR 4/8 at 3.5",	loamy, gravelly, medium
		dark grey brown	25%, large	sand, friable, sulfidic odor

Sketch approximate mitigation site, noting areas and types of wetlands, waters, other features, landscape position, landmarks, etc., and data and photo point(s):

Drawings are with field notes.


### **Overall Description of site:**

The site consists of two ponded areas that are separated by wooded upland. On the west side of Site A there is a forested wetland. Residential areas are to the north and commercial areas are to the south and east. Site C has residential to the north and west and swamp to the east and south. Site C was too wet to get a decent soil sample; it is basically a pond surrounded by steep banks.

## **Comments, problems, recommendations:**

Water depths were not taken though it appears from the mitigation file that this might be a concern. Both sites had what seemed to be deep water.

Site A is the site farthest away from Route 1. Site C is the site nearest Route 1.



# Wetland Function-Value Evaluation Form

0.40						Wetland I.D. David Cash 179701040	
Total area of wetland_~0.43 ac_ Human made?yes Is wetland part of a wildlife corridor?no or a "habitat island"?_yes						Latitude N41.96885 Longitude W71.33749	
Adjacent land use residential, industrial park		Distance to nearest roadway or other development_10 feet			Prepared by: RL PM Date 5/14/03		
Dominant wetland systems present_PEM, POW	20% but only Contiguous undeveloped buffer zone present about 100 feet wide			Wetland Impact: TypeArea			
Is the wetland a separate hydraulic system? yes	3	_ If not,	where does the wetland	lie in the dr	rainage basin? n/a	Evaluation based on: Office X Field	
How many tributaries contribute to the wetland? 0			ildlife & vegetation diver	rsity/abund	ance (see attached list)	Corps manual wetland delineation	
Function/Value		ability N	Rationale (Reference #)*	Princi Funct		completed? Y N_X	
▼ Groundwater Recharge/Discharge	X				it is likely that both recharge and d	scharge occur	
Floodflow Alteration		X					
Fish and Shellfish Habitat		X			too small and too shallow		
Sediment/Toxicant Retention	X			X	minimal		
Nutrient Removal		X					
→ Production Export		X					
Sediment/Shoreline Stabilization		X					
<b>₩</b> Wildlife Habitat	X			X	adjacent to forested wetland system	n but limited by size and proximity to development	
A Recreation		X					
Educational/Scientific Value		X					
★ Uniqueness/Heritage		X					
Visual Quality/Aesthetics		X					
ES Endangered Species Habitat		X			none known		
Other							

Notes:

<sup>\*</sup> Refer to backup list of numbered considerations.

199701040 David Cash N. Attleboro, MA 6/20/02



Area A from south side



Area A erosion on northeast edge. Note steepness of slope.



Area A vegetation plot from west end looking east



Area C facing southwest with Route 1 in the background. Domino's Pizza is off the photo to the left.

**■USGS** North Attleboro, Massachusetts, United States 29 Mar 1995

Image courtesy of the U.S. Geological Survey © 2003 Microsoft Corporation. All rights reserved.

200yd كىت

**—**200М